

## Parts needed to mount the PDS-4-K extrusion




## **Tools needed for mounting:**

- mounting glue

**WARNING!** All LED strips should be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.eu



KLUŚ<sub>®</sub> Inspiring Solutions