




Parts needed to mount the KRAV-810 extrusion



Extrusion (A and B)



End cap (C)




LED strip (E)


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.KlusDesign.eu


- 1.** Mount the LED strip (E) at the top of the extrusion (B) and lead out the power cable.




- 3.** Degrease the glass and attach the upper part of the extrusion (B).



- 4.** Attach the lower part of the extrusion (B).



- 5.** Insert the end cap (C).



- 6.** Connect power.

