


Parts needed to mount the KOZUS extrusion



Tools needed for mounting:


- mounting glue

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.eu

www.KlusDesign.eu 1





www.KlusDesign.eu 2